UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION IX
75 Hawthorne Street
San Francisco, Ca. 94105-3901

December 2, 1991

MEMORANDUM

SUBJECT: Final Report by Cerrillos Land Company, Clean-up Action on Section 19, T13N, R10W of McKinley County.

FROM: Robert Bornstein RB
Federal On-Scene-Coordinator

TO: Bill Nelson, ATSDR (for distribution among ATSDR)
Ray Churan, DOI (for distribution among DOI agencies)
Stan Edison, Navajo Superfund (for distribution)
Linda Wandres, ORC
Bob Ivey, DOE

Enclosed is a copy of the post-removal report by Cerrillos Land Company. The report was submitted to EPA pursuant to EPA Order 91-16. If you need a copy of the post removal contour map please request a copy from Mr. Paul Eby of Cerrillos Land Company at 505-880-5300. Their post removal survey indicates that the site's gamma radiation levels have been significantly reduced to below 71 uR/hr (50 uR/hr divided by their instrument conversion factor of .7). Overall, within the reclamated areas, the section is reading approximately 28 uR/hr.

If you have any questions regarding this report, please contact me at 415-744-2298.

Cerrillos Land Company

6200 Uptown Blvd. N.E., Suite 400
Albuquerque, New Mexico 87110
Box 27019
Albuquerque, New Mexico 87125
505/880-5300 Fax# 505/880-5435

POST RESPONSE REPORT

EPA ORDER 91-16

Receipt of Order

On August 5, 1991, Cerrillos Land Company received EPA Order 91-16. This order designated Cerrillos as a potentially responsible party for elevated gamma radiation from uranium sub-ore grade mine waste and large shallow open pits located in the NW 1/4, Section 19, Township 13N, Range 10W of McKinley County, New Mexico, where Cerrillos retains ownership of the mineral rights. The basis of this order was for Cerrillos to reduce the potentially hazardous gamma emissions from the site to a level acceptable to all agencies concerned (165 uR/hr above background or to a total of 180 uR/hr) in order to remediate potential health risk to families living nearby.

Acceptance of Order

As provided for in the order, Cerrillos Land Company requested a conference with EPA representatives in order to determine the exact nature of the order, for legal clarification and for guidelines on how to proceed. This accomplished, Cerrillos accepted the order on August 28, 1991, and proceeded with compliance.

Submittal of Site Work Plan - Health and Safety Plan

On August 28, 1991, a final Site Work Plan and Site Health and Safety Plan, detailing actions necessary to comply with the order, were submitted for approval. Included with the Work Plan was the pre-response gamma survey map, statement of qualifications for the contractor selected and statement of

Contractor Personnel and Equipment

Taylor Services of Grants, New Mexico, was the contractor selected by Cerrillos for site stabilization work. They have provided excellent, responsive and cost effective work on a very complex project. Key personnel are listed below:

Larry Taylor - Owner - Superintendent
Tony Canaba - Foreman - Operator
Dale Rowe - Operator
Paul Rowe - Operator
Mike McGinn - Operator
Rudy Purilla - Operator
Richard Grey - Operator
Raul Zapata - Driver
Multiple - Laborers

The primary equipment provided by Taylor Services for this project was either new or substantially equivalent to new. All equipment listed below was not run continuously, but on an as-needed basis.

3 - D-8 size Bulldozers
1 - D-6 size Bulldozer
1 - Front-End Loader (6 yd.)
1 - Road Grader
1 - End-Dump Truck
3 - Belly-Dump Trucks (Sub-contract)
1 - Office Trailer - Lunchroom

Contractor compliance with the Health and Safety Plan was excellent. Primary equipment had pressurized cabs and all equipment had back-up horns. Personnel wore hard hats, safety shoes or boots, safety glasses, radiation badges, and

During the second and third weeks of September, several more pieces of machinery were added and the project schedule accelerated to the maximum manageable level. Work proceeded, as planned, with only minor deviations. Some material had to be moved or covered two or more times to achieve acceptable readings. Mass effect in a larger area such as this proved difficult. Also, every effort was made to save as many Juniper and Piñon trees as possible. By mid-November, all areas were covered, contoured and made ready for the post-response survey and subsequent seeding.

Post Response Survey

The post-response radiometric survey over the property was performed by first laying out a 250′ x 250′ control grid over the area of disturbance. This was done with the use of a Brunton compass, tripod and a 300′ tape. At that point, each 250′ grid was internally divided into a 50′ grid, again utilizing the 300′ tape and setting pin flags at all points. Four Ludlum model 19 instruments, each calibrated against its own check source, were then used for the survey. This was performed using a measuring line and four men, each with an instrument held at a height of one meter above the ground and walking on 12 1/2′ centers on east-west lines to cover the entire property. At 50′ intervals, the highest reading from each instrument for that line was recorded on a chart. This then provided five line readings for 50′ grid, the highest of which was then recorded on the grid map provided as the final post-response survey.

The 500′ x 500′ grid sections on this map are numbered to correspond with the pre-response survey map submitted previously. Copies of each are submitted with this report. For your further edification, we are submitting the 500′ x 500′ grid charts showing line readings for each of the 50′ x 50′ grids.

Project Cost

Approximate expenditures on the project for all direct charged costs are as follows:

Title Work	$ 5,188
Ground Survey	7,142
Aerial Survey & Mapping	3,690
Instruments	5,515
On-Site Coordinator & Technician	17,670
Dirt Contractor	175,305
Seed	5,822
Miscellaneous	2,383
DIRECT PROJECT COST	$222,715

Conclusion of Report

Affidavit attached.

HAYSTACK MOUNTAIN PROJECT

Grid No. 1 Date

		18 14 16 14	18 24 32 18	22 12 26 26	24 16 28 34	20 20 20 16	16 16 28 22	14 14 32 18	12 16 32 16
		16 14 15 16	28 26 24 22	30 32 30 26	24 24 24 22	18 20 22 20	16 20 20 36	20 22 20 20	20 22 17 22
		24 19 16 22	20 17 17 18	21 21 20 20	30 26 22 26	22 22 42 22	44 22 40 18	20 22 24 20	22 22 42 26
		34 30 42 22	22 46 44 32	24 26 28 24	30 20 22 18	22 16 16 16	18 18 24 22	28 26 28 24	20 20 20 18
		22 20 22 26	28 20 24 20	38 32 26 32	22 28 26 24	18 18 18 16	18 18 28 20	28 26 24 22	20 20 22 26

HAYSTACK MOUNTAIN PROJECT

Grid No. 3 Date

14 12 16 12	14 16 16 14								

HAYSTACK MOUNTAIN PROJECT

Grid No. 5 **Date** _____



HAYSTACK MOUNTAIN PROJECT

Grid No. 7 **Date** ______________

22 12 [illegible] 20	18 20 20 12	20 22 22 22	18 22 22 26	24 20 28 22	18 22 22 22	[illegible] 20 20 22	12 [illegible] 22 28	[illegible] 20 [illegible] [illegible]	[illegible] 20 22 22
26 28 [illegible] 18	[illegible] [illegible] [illegible] 22	20 [illegible] [illegible] 22	[illegible] [illegible] [illegible] [illegible]	20 22 26 20	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] [illegible]
18 22 26 20	[illegible] 18 20 [illegible]	22 22 22 22	28 28 22 28	28 20 20 22	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] [illegible]		
24 20 28 26	22 [illegible] 26 22	26 22 22 20	30 20 36 32	26 28 34 20	18 20 20 18	20 22 18 20	[illegible] [illegible] [illegible] 18		
26 20 22 18	20 24 28 20	20 18 20 18	30 22 18 16	22 22 28 16	18 18 20 20				
20 17 18 18	24 26 17 18	20 19 18 22	20 18 16 20	22 24 26 14	24 22 20 18	24 20 18 16	30 22 22 17	24 22 20 20	
28 26 26 20	22 26 24 28	20 22 [illegible] 20	24 27 29 28	18 17 16 16	18 16 18 16	[illegible] [illegible] 17 14	24 22 24 22		
24 22 28 24	26 30 32 18	26 28 30 20	28 30 32 24	22 28 24 24	20 24 28 36	24 40 28 38	26 30 40 26		
22 20 [illegible] 12	20 28 32 28	24 22 24 22	22 20 26 22	20 24 22 24	32 28 28 26	30 30 28 22	32 40 32 20		
24 30 28 25	34 20 24 20	30 32 32 32	26 24 24 24	22 22 24 22	28 28 26 26	32 30 36 28	32 30 34 [illegible]	27 20 17 20	22 17 [illegible] 14

HAYSTACK MOUNTAIN PROJECT

Grid No. 9

Date _____

HAYSTACK MOUNTAIN PROJECT

Grid No. 11 Date

16 12 12 12	20 12 12 12	24 12 12 12	28 20 20 16	26 22 26 20	24 26 29 22	24 24 24 20	22 22 18 12	18 18 18 12	18 18 18 18
6 12 12 12	12 12 12 12	12 18 20 12	20 12 12 12	22 12 12 12	20 22 20 12	22 12 12 12	12 12 12 12	26 24 22 22	18 18 18 18
16 10 12 10	12 12 12 10	22 12 12 10	18 16 14 10	12 12 12 12	12 12 12 18	12 12 12 14	12 12 12 10	12 12 12 34	12 12 12 12
12 10 11 10	12 14 16 12	14 12 12 14	16 14 14 14	12 12 12 16	14 12 12 12	14 14 12 14	12 12 12 16	12 20 12 16	12 12 12 20
12 12 11 12	12 10 10 12	12 12 14 12	12 14 14 14	12 12 12 12	14 16 14 16	16 14 16 16	16 14 16 20	14 14 16 16	18 16 14 14
14 16 10 11	12 10 11 10	12 11 11 9	14 12 14 14	14 12 14 12	16 12 16 12	13 12 14 16	12 12 20 16	12 12 12 12	12 12 12 12
14 10 12 10	12 12 12 10	12 12 12 12	12 12 12 12	12 12 12 12	14 14 12 12	16 12 12 12	16 16 16 20	16 16 16 16	16 16 16 16
14 10 10 12	14 10 9 10	12 12 12 12	20 18 16 20	12 16 22 12	20 24 20 20	12 20 18 14	20 22 12 16	22 22 24 22	16 20 20 16
12 12 12 10	14 12 12 10	14 12 11 10	22 22 20 16	16 16 12 14	24 22 16 14	16 12 14 12	16 16 16 12	22 22 22 22	24 18 20 20
12 12 10 10	12 12 12 12	12 12 12 10	16 12 12 16	12 20 12 14	20 20 16 16	20 12 14 14	20 20 12 14	24 22 20 20	22 20 22 22

HAYSTACK MOUNTAIN PROJECT

Grid No. 13 **Date**

12 18 12 12									
20 [illegible] [illegible] [illegible]	22 [illegible] [illegible] [illegible]								
[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] 22	22 20 22 30							
32 28 30 26	[illegible] 26 [illegible] 32	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] 22 24	[illegible] [illegible] [illegible] 20	[illegible] [illegible] [illegible] 20	[illegible] [illegible] 28			
22 18 16 18	22 18 22 20	[illegible] 34 42 36	40 40 46 40	32 34 28 40	[illegible] [illegible] [illegible] [illegible]	[illegible] [illegible] [illegible] 40	22 20 22 26	20 18 16 22	[illegible] [illegible] [illegible] [illegible]
30 20 26 22	22 18 16 20	26 20 18 16	34 32 32 34	32 30 30 30	34 26 28 26	40 34 32 34	28 [illegible] [illegible] 28	32 28 [illegible] [illegible]	[illegible] [illegible] [illegible] 26
26 22 [illegible] [illegible]	22 20 32 24	30 26 20 22	24 20 [illegible] 26	28 24 26 24	28 26 30 28	[illegible] [illegible] [illegible] 22	26 28 [illegible] 22	32 26 [illegible] 24	[illegible] [illegible] [illegible] [illegible]
28 30 24 34	22 26 28 30	28 24 30 30	24 24 24 24	28 24 26 36	30 26 26 28	30 [illegible] [illegible] 32	30 28 34 32	[illegible] [illegible] [illegible] 32	30 [illegible] [illegible] 24
38 36 [illegible] 32	40 42 40 34	32 30 46 36	34 28 34 36	30 30 28 30	32 26 32 30	[illegible] 30 [illegible] 32	42 40 40 34	36 28 34 36	[illegible] [illegible] 26 34
30 [illegible] 24 26	36 28 22 24	38 40 [illegible] 32	30 28 30 26	[illegible] 30 28 27	30 30 26 24	40 32 28 26	40 24 24 24	22 20 22 20	[illegible] [illegible] [illegible] [illegible]

HAYSTACK MOUNTAIN PROJECT

Grid No. 15 Date _____

HAYSTACK MOUNTAIN PROJECT

Grid No. 17 Date _____

HAYSTACK MOUNTAIN PROJECT

Grid No. 19 Date

HAYSTACK MOUNTAIN PROJECT

Grid No. 21 Date _____

HAYSTACK MOUNTAIN PROJECT

Grid No. 23 Date

22 12 22 22	26 22 24 22	20 20 22 20	32 20 20 20	30 26 30 28	24 40 22 26	20 16 12	26 12 28 20	22 30 24 26	30 22 24 20
22 20 22 22	22 20 22 22	22 20 22 22	22 20 12 12	22 20 12 12	20 20 12 20	22 12 12 12	20 12 20 24	24 12 20 20	22 20 22 20
22 20 22 24	22 12 22 22	26 20 22 22	22 20 24 22	26 20 22 24	12 16 12 20	12 12 20 20	22 22 12 24	22 26	24 22
32 22 22 26	22 20 24 20	20 22 18 18	26 24 24 20	26 12 20 12	16 20 24 22	12 12 18 14	24		
40 34 22 22	28 24 30 26	22 12 20 22	16 16 12 20	20 18 30 28	16 18 22 12	32 24 26 22			
22 20 22 18	24 22 24 22	28 28 22 30	24 20 26 24	16 22 24	22 26	20			
20 12 20 12	24 24 20 22	28 30 22	30 20	22 26					
16 14 22 22	14 22 22								